

APPLICANT	Condron Constructions 5 Hickory PI SPRINGVALE NSW 2650					
SUBJECT LAND	ADDRESS:					
	9 Quill Ave BOOROOMA NSW 2650					
	LOT/DP : Lot 628 DP 1241474					
CERTIFICATE NO.	CDC20/0044 DATE OF ISSUE : 17/03/2020					
TYPE OF	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.					
CERTIFICATE	[]	Footing	[]	Frame	[]	Floor Slab
	[]	Wet area flashing	[]	Sub floor frame	[]	Stormwater drainage
	[]	Internal drainage	[]	External drainage	[]	Trade Waste
	[]	Stackwork	[]	Final plumbing	[]	Pool backwash
	[X]	Piers				
	Other [X] Conditions have been complied with Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with. Comments:					
		•	•••••	•••••	• • • • • • • • • • • • • • • • • • • •	
DETERMINATION OF CERTIFICATE						
	Wagga Wagga City Council confirms that:					
	[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.					
	[X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons:					
	·					
	Inspection Date:		24/03/2020			
	Name of Council Officer: BPB Accreditation No:		Mason, Andrew			
			3352			
	Council User ID:		MASONANDREWJ			

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.