

APPLICANT	Condron Constructions 5 Hickory PI SPRINGVALE NSW 2650		
SUBJECT LAND	ADDRESS: 9 Quill Ave BOOROOMA NSW 2650		
	LOT/DP : Lot 628 DP 1241474		
CERTIFICATE NO.	CDC20/0044 DATE OF ISSUE : 17/03/2020		
TYPE OF	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
CERTIFICATE	[] Footing	[] Frame	[X] Floor Slab
	[] Wet area flashing	[] Sub floor frame	[] Stormwater drainage
	[] Internal drainage	[] External drainage	[] Trade Waste
	[] Stackwork	[] Final plumbing	[] Pool backwash
	[] Piers		
	Other		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	Comments:		
			
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:		
	[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.		
	[X] The above condition(s) have been complied with and works can continue.		
	[] The Compliance Certificate is FAILED for the following reasons:		
	Inspection Date:	06/04/2020	
	Name of Council Officer:	Mason, Andrew	
	BPB Accreditation No:	3352	
	Council User ID:	MASONANDREWJ	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.