

APPLICANT	JD White 90 Thorne St WAGGA WAGGA NSW 2650		
SUBJECT LAND	ADDRESS: 90 Thorne St WAGGA WAGGA NSW 2650		
	<b>LOT/DP</b> : Lot 12 DP 1347		
CERTIFICATE NO.	CC20/0067 <b>DATE OF ISSUE</b> : 24/04/2020		
TYPE OF CERTIFICATE	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
	[ ] Footing	[ ] Frame	[ ] Floor Slab
	[ ] Wet area flashing	[ ] Sub floor frame	[ ] Stormwater drainage
	[ ] Internal drainage	[ ] External drainage	[ ] Trade Waste
	[ ] Stackwork	[ ] Final plumbing	[ ] Pool backwash
	[X] Other pool coping		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	concrete coping be council.	am. Ensure fencing is completed as per a	approved plans and final booked with
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:		
	<ul> <li>[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.</li> <li>[X] The above condition(s) have been complied with and works can continue.</li> <li>[ ] The Compliance Certificate is FAILED for the following reasons:</li> </ul>		
	Inspection Date:	20/05/2020	
	Name of Council Officer:	Stanic, Luka	
	BPB Accreditation No:	2359	
	Council User ID:	stanicl	

NOTE: This inspection was completed using an electronic device