

Issued under the Plumbing and Drainage Act 2011 & Local Government Act 1993 & Local Government (General) Regulation 2005

| | | _ |
|---------------------------------|--|-----|
| APPLICANT | Cooke & Dowsett (Albury) Pty Ltd Po Box 7332 EAST ALBURY NSW 2640 | |
| SUBJECT LAND | ADDRESS: OWNER: | _ |
| | 56 Estella Rd CHARLES STURT UNIVERSITY NSW 2678 Minister for Education and Early | |
| | LOT/DP: Lot 1 DP 1253855 Childhood Learning | |
| CERTIFICATE NO. | AA20/0201 DATE OF ISSUE: 09/07/2020 | |
| TYPE OF | [X] Specified building/subdivision work has been completed and complies with the plans and specifications | |
| CERTIFICATE | [X] Internal drainage [X] External drainage [] Stormwater drainage | |
| | [] Stackwork [] Final plumbing [] Trade Waste | |
| | [] Pool backwash [] Septic Installations with AA [] Int / Ext Sewer Stormwater | |
| | [] Interim Occupancy [] Site Inspection | |
| | | |
| | [] Other Other Inspection Type: | |
| | [X] Conditions have been complied with | |
| | Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with. | |
| | 1. Certificate No.: AA20/0201 | • |
| | 2. Plumbing Code of Aust | |
| | 3. AS3500 Block A Int / Ext drainage | |
| | | : |
| | | |
| | <u> </u> | ••• |
| DETERMINATION OF CERTIFICATE | Wagga Wagga City Council confirms that: | _ |
| | [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. | |
| | requirement relened to above. | |
| | [X] The above condition(s) have been complied with. | |
| | [] The Compliance Certificate is REFUSED for the following reasons: | |
| | : | : |
| | | : |
| | | : |
| | | : |
| | | : |
| | | _ |
| | Inspection Date: 09/07/2020 | |
| | Name of Council Officer: Stanic, Luka | |
| | Council User ID: stanicl | |
| | | |

NOTE: This inspection was completed using an electronic device