



APPLICANT	C Cartwright 502 Kooringal Rd LAKE ALBERT NSW 2650		
SUBJECT LAND	ADDRESS:		
	502 Kooringal Rd LAKE ALBERT NSW 2650		
	LOT/DP: Lot 5 DP 231977		
CERTIFICATE NO.	CC20/0037 DATE OF ISSUE: 30/03/2020		
TYPE OF	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
CERTIFICATE	[] Footing	[] Frame	[X] Floor Slab
	[ ] Wet area flashing	[ ] Sub floor frame	[ ] Stormwater drainage
	[] Internal drainage   [] Stackwork	[] External drainage	[ ] Trade Waste [ ] Pool backwash
	[ ] Stackwork [X] Piers	[ ] Final plumbing	[ ] Pool backwash
	Other		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	Comments:		
	Comments.		
	÷		
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:		
	[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.		
	[X] The above condition(s) have been complied with and works can continue.		
	[ ] The Compliance Certificate is FAILED for the following reasons:		
		······································	
	••••••		
	Inspection Date:	10/07/2020	
	Name of Council Officer:	Butt, Christopher	
	BPB Accreditation No:	3231	
	Council User ID:	BUTTC	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.