

APPLICANT	FA Mullins PO Box 164 WAGGA WAGGA NSW 2650		
SUBJECT LAND	ADDRESS: 34 Athol St TURVEY PARK NSW 2650		
	<b>LOT/DP</b> : Lot 5 Sec 3 DP 12786		
CERTIFICATE NO.	CC20/0027 <b>DATE OF ISSUE:</b> 15/05/2020		<b>DATE OF ISSUE:</b> 15/05/2020
TYPE OF CERTIFICATE	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
	[X] Footing	[ ] Frame	[ ] Floor Slab
	[ ] Wet area flashing	Sub floor frame	[ ] Stormwater drainage
	[ ] Internal drainage [ ] Stackwork	[ ] External drainage	[ ] Trade Waste [ ] Pool backwash
	[ ] Stackwork	[ ] Final plumbing	[ ] Pool backwash
	Other		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	Comments: Please	submit site survey for fencing as per con	•
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:		
	<ul> <li>[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.</li> <li>[X] The above condition(s) have been complied with and works can continue.</li> <li>[] The Compliance Certificate is FAILED for the following reasons:</li> </ul>		
	Inspection Date:	21/09/2020	
	Name of Council Officer:	Brockbank, Joshua	
	BDC Registration No:	3253	
	Council User ID:	Brockbankj	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.