

APPLICANT	MP Hunt 24 Macleay St TURVEY PARK NSW 2650		
SUBJECT LAND	ADDRESS: 24 Macleay St TURVEY PARK NSW 2650 LOT/DP: Lot 18 DP 224340		
CERTIFICATE NO.	CC20/0236 DATE OF ISSUE: 05/08/2020		
TYPE OF	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
CERTIFICATE	[X] Footing	[] Frame	[] Floor Slab
	[] Wet area flashing	[] Sub floor frame	[] Stormwater drainage
	[] Internal drainage	[] External drainage	[] Trade Waste
	[] Stackwork	[] Final plumbing	[] Pool backwash
	[X] Piers		
	Other		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	Comments: Ensure additional vents	adequate ventilation is provided for the n	ew part being constructed by adding
DETERMINATION	Wagga Wagga City Council confirms that:		
OF CERTIFICATE	 [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. [X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons: 		
	Inspection Date:	02/11/2020	
	Name of Council Officer: Brockbank, Joshua		
	BDC Registration No:	3253	
	Council User ID:	Brockbankj	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.