



APPLICANT	AS Metcalf 59 Kiincaid Street WAGGA WAGGA NSW 2650			
SUBJECT LAND	ADDRESS: 59 Kincaid St WAGGA WAGGA NSW 2650 LOT/DP: Lot 1 DP 563586			
CERTIFICATE NO.	CC20/0087 DATE OF ISSUE: 27/05/2020			
TYPE OF CERTIFICATE	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.			vith the plans and specifications.
	[] Footing	[X] Frame	[]	Floor Slab
	[] Wet area flashing	[] Sub floor fram	e []	Stormwater drainage
	[] Internal drainage	[] External drain	age []	Trade Waste
	[] Stackwork	[] Final plumbing	ı []	Pool backwash
	[] Piers			
	Other			
	[X] Conditions have been complied with			
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.			
	Comments: Wall bracing on ground and upper storey, roof truss tie down, steel framing to details for two storey addition. Ensure internal ceiling heights are as per approved plans. Continue as per approved plans, BASIX, conditions of the consent.			
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:			
	[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.			
	[X] The above condition(s) have been complied with and works can continue.			
	[] The Compliance Certificate is FAILED for the following reasons:			
	<u>i</u> i			
	Inspection Date: 01/12/2020			
	Name of Council Officer: Stanic, Luka			
	BDC Registration No: 2359			
	Council User ID:	stanicl		

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.