

APPLICANT	FA Mullins PO Box 164 WAGGA WAGGA NSW 2650		
SUBJECT LAND	ADDRESS: 34 Athol St TURVEY PARK NSW 2650 LOT/DP: Lot 5 Sec 3 DP 12786		
CERTIFICATE NO.	CC20/0027 DATE OF ISSUE: 15/05/2020		
TYPE OF	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
CERTIFICATE	[] Footing	[X] Frame	[] Floor Slab
	[] Wet area flashing	[] Sub floor frame	[] Stormwater drainage
	[] Internal drainage	[] External drainage	[] Trade Waste
	[] Stackwork	[] Final plumbing	[] Pool backwash
	Othor		
	[X] Conditions have been complied with		
		pecified condition(s) of the development of condition relates to and the standards/ins	
		nd roof frame to the detached garage bloc nout two windows to the pool area.	k to manufacturer's detail. Provide revised
DETERMINATION	Wagga Wagga City Council confirms that:		
OF CERTIFICATE	 [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. [X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons: 		
	Inspection Date:	22/01/2021	
	Name of Council Officer:	Jayasekera, Prasad	
	BDC Registration No:	2982	
	Council User ID:	JAYASEKERAP	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.