



City of Wagga Wagga

INSPECTION REPORT

| | | | | | | |
|-------------------------------------|--|-------------------|----------------------------------|-------------------|-----|---------------------|
| APPLICANT | TV Wilson 34 Atherton Cres TATTON NSW 2650 | | | | | |
| SUBJECT LAND | ADDRESS: 34 Atherton Cres TATTON NSW 2650 LOT/DP: Lot 11 DP 1029543 | | | | | |
| CERTIFICATE NO. | CC20/0381 | | DATE OF ISSUE: 10/11/2020 | | | |
| TYPE OF CERTIFICATE | [X] Specified building/subdivision work has been completed and complies with the plans and specifications. | | | | | |
| | [X] | Footing | [] | Frame | [] | Floor Slab |
| | [] | Wet area flashing | [] | Sub floor frame | [] | Stormwater drainage |
| | [] | Internal drainage | [] | External drainage | [] | Trade Waste |
| | [] | Stackwork | [] | Final plumbing | [] | Pool backwash |
| | [] | Piers | | | | |
| | Other | | | | | |
| | [X] Conditions have been complied with | | | | | |
| | Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with. | | | | | |
| | <div style="border: 1px dotted black; padding: 5px;"> Comments: </div> | | | | | |
| DETERMINATION OF CERTIFICATE | Wagga Wagga City Council confirms that: | | | | | |
| | [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. | | | | | |
| | [X] The above condition(s) have been complied with and works can continue. | | | | | |
| | [] The Compliance Certificate is FAILED for the following reasons: | | | | | |
| | <div style="border: 1px dotted black; height: 80px; width: 100%;"></div> | | | | | |
| | Inspection Date: 21/03/2021 Name of Council Officer: Foster, Kira-Lee BDC Registration No: 0974 Council User ID: fosterk | | | | | |

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.