

APPLICANT	FA Mullins PO Box 164 WAGGA WAGGA NSW 2650		
SUBJECT LAND	ADDRESS: 34 Athol St TURVEY PARK NSW 2650		
	LOT/DP: Lot 5 Sec 3 DP 12786		
CERTIFICATE NO.	CC20/0027 DATE OF ISSUE : 15/05/2020		
TYPE OF	[X] Specified building/subdivision work has been completed and complies with the plans and specifications.		
CERTIFICATE	[] Footing	[] Frame	[] Floor Slab
	[X] Wet area flashing	Sub floor frame	Stormwater drainage
	[] Internal drainage	[] External drainage [] Final plumbing	[] Trade Waste [] Pool backwash
	[] Stackwork	[] Final plumbing	[] TOOLDACKWASII
	Other		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	Comments: Inspec	tion inclusive of wet area to pool house	
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:		
	 [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. [X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons: 		
	Inspection Date:	30/03/2021	
	Name of Council Officer:	Mason, Andrew	
	BDC Registration No:	3352	
	Council User ID:	MASONANDREWJ	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.