

APPLICANT	JDJ Demczyszyn 35 Goborra St GLENFIELD PARK NSW 2650		
SUBJECT LAND	ADDRESS: 35 Goborra St GLENFIELD PARK NSW 2650		
	LOT/DP: Lot 213 DP 262586		
CERTIFICATE NO.	CC23/0157 DATE OF ISSUE: 18/04/2023		
TYPE OF CERTIFICATE	[] Footing [] Wet area flashing [] Internal drainage [] Stackwork [X] Piers	livision work has been completed and cor [] Frame [] Sub floor frame [] External drainage [] Final plumbing	[X] Floor Slab[] Stormwater drainage[] Trade Waste[] Pool backwash
	[X] Conditions have been complied with Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with. Comments: Slab as per engineers design and detail - ok to proceed		
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that: [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. [X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons:		
	Inspection Date: Name of Council Officer: BDC Registration No:	27/04/2023 Butt, Christopher 3231	
	Council User ID:	BUTTC	

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.