

APPLICANT	IR Winbank & GB Smith 38 Slocum St WAGGA WAGGA NSW 2650		
SUBJECT LAND	ADDRESS: 43 Valencia Dr GOBBAGOMBALIN NSW 2650 LOT/DP: Lot 307 DP 1281704		
CERTIFICATE NO.	CC23/0161 DATE OF ISSUE: 01/05/2023		
TYPE OF CERTIFICATE	<del> </del>	livision work has been completed and cor	· · · · · · · · · · · · · · · · · · ·
CERTIFICATE	[ ] Footing	[ ] Frame	[ ] Floor Slab
	[ ] Wet area flashing [ ] Internal drainage	[ ] Sub floor frame [ ] External drainage	[ ] Stormwater drainage [ ] Trade Waste
	[ ] Stackwork	[ ] Final plumbing	[ ] Pool backwash
	[ ] Piers	[ ] I man pramising	[ ] Tool baskmash
	[X] Other pool bond beam		
	[X] Conditions have been complied with		
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.		
	*		······································
DETERMINATION OF CERTIFICATE			
	Wagga Wagga City Council confirms that:		
	[X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.		
			n continuo
	[X] The above condition(s) have been complied with and works can continue.		
	[ ] The Compliance Certificate is FAILED for the following reasons:		
	<b>:</b>		:
	Inspection Date:	22/05/2023	
	Name of Council Officer:	Tyson, Kelly	
	BDC Registration No:	3289	
	Council User ID:	TYSONK	

NOTE: This inspection was completed using an electronic device