

APPLICANT	MAC Wagga Pty Ltd 11 Mitta Mitta Pl GOBBAGOMBALIN NSW 2650
SUBJECT LAND	ADDRESS: 50 Peppermint Dr SPRINGVALE NSW 2650
	LOT/DP: Lot 68 DP 1073172
CERTIFICATE NO.	CC23/0125 DATE OF ISSUE: 21/04/2023
TYPE OF CERTIFICATE	[X] Specified building/subdivision work has been completed and complies with the plans and specifications. [] Footing [] Frame [] Floor Slab [] Wet area flashing [] Sub floor frame [] Stormwater drainage [] Internal drainage [] External drainage [] Trade Waste [] Stackwork [] Final plumbing [] Pool backwash [X] Other Pool Bond Beam [X] Conditions have been complied with Give details of the specified condition(s) of the development of the development of the detail of the matter the condition relates to and the standards/instruments that the matter is required to comply with. Swimming pool bond beam inspection satisfactory
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that: [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. [X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons:
	Inspection Date: 27/07/2023 Name of Council Officer: Singh, Pardeep BDC Registration No: 4867 Council User ID: SINGHP

NOTE: This inspection was completed using an electronic device