

| APPLICANT | Matt Jenkins Builder Pty Ltd 18 Dobney Ave WAGGA WAGGA NSW 2650 | | |
|---------------------------------|---|-----------------------|-------------------------|
| SUBJECT LAND | ADDRESS: 21 Paroo PI TATTON NSW 2650 | | |
| | LOT/DP : Lot 20 DP 1291851 | | |
| CERTIFICATE NO. | CC23/0219 DATE OF ISSUE: 20/06/2023 | | |
| TYPE OF | [X] Specified building/subdivision work has been completed and complies with the plans and specifications. | | |
| CERTIFICATE | [] Footing | [X] Frame | [] Floor Slab |
| | [] Wet area flashing | [] Sub floor frame | [] Stormwater drainage |
| | [] Internal drainage | [] External drainage | [] Trade Waste |
| | [] Stackwork [] Piers | [] Final plumbing | [] Pool backwash |
| | | | |
| | [X] Conditions have been complied with | | |
| | Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with. Comments:Frame and truss to manufacturers specification | | |
| | *************************************** | | |
| DETERMINATION OF CERTIFICATE | Wagga Wagga City Council confirms that: | | |
| | [X] The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. [X] The above condition(s) have been complied with and works can continue. [] The Compliance Certificate is FAILED for the following reasons: | | |
| | | | |
| | | | ; |
| | | | |
| | Inspection Date: | 05/10/2023 | |
| | Name of Council Officer: | Foster, Kira-Lee | |
| | BDC Registration No: | 0974 | |
| | Council User ID: | fosterk | |

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.