



City of Wagga Wagga

INSPECTION REPORT

APPLICANT	DL Van Der Rijt 68 Thorne St WAGGA WAGGA NSW 2650																			
SUBJECT LAND	ADDRESS: 86 Johnston St WAGGA WAGGA NSW 2650 LOT/DP: Lot 1 DP 718354																			
CERTIFICATE NO.	CC22/0331.01		DATE OF ISSUE: 17/04/2023																	
TYPE OF CERTIFICATE	<input checked="" type="checkbox"/> Specified building/subdivision work has been completed and complies with the plans and specifications. <table border="1"> <tr> <td><input type="checkbox"/> Footing</td><td><input type="checkbox"/> Frame</td><td><input type="checkbox"/> Floor Slab</td></tr> <tr> <td><input checked="" type="checkbox"/> Wet area flashing</td><td><input type="checkbox"/> Sub floor frame</td><td><input type="checkbox"/> Stormwater drainage</td></tr> <tr> <td><input type="checkbox"/> Internal drainage</td><td><input type="checkbox"/> External drainage</td><td><input type="checkbox"/> Trade Waste</td></tr> <tr> <td><input type="checkbox"/> Stackwork</td><td><input type="checkbox"/> Final plumbing</td><td><input type="checkbox"/> Pool backwash</td></tr> <tr> <td><input type="checkbox"/> Piers</td><td></td><td></td></tr> </table> <p>Other</p> <p><input checked="" type="checkbox"/> Conditions have been complied with</p> <p>Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.</p> <div style="border: 1px dotted black; padding: 5px;"> <p>Comments: Waterproofing new area satisfactory except WC which is required to be done and inspected and existing building waterproofing to be inspected. Continue as per development consent and approved plans</p> </div>					<input type="checkbox"/> Footing	<input type="checkbox"/> Frame	<input type="checkbox"/> Floor Slab	<input checked="" type="checkbox"/> Wet area flashing	<input type="checkbox"/> Sub floor frame	<input type="checkbox"/> Stormwater drainage	<input type="checkbox"/> Internal drainage	<input type="checkbox"/> External drainage	<input type="checkbox"/> Trade Waste	<input type="checkbox"/> Stackwork	<input type="checkbox"/> Final plumbing	<input type="checkbox"/> Pool backwash	<input type="checkbox"/> Piers		
<input type="checkbox"/> Footing	<input type="checkbox"/> Frame	<input type="checkbox"/> Floor Slab																		
<input checked="" type="checkbox"/> Wet area flashing	<input type="checkbox"/> Sub floor frame	<input type="checkbox"/> Stormwater drainage																		
<input type="checkbox"/> Internal drainage	<input type="checkbox"/> External drainage	<input type="checkbox"/> Trade Waste																		
<input type="checkbox"/> Stackwork	<input type="checkbox"/> Final plumbing	<input type="checkbox"/> Pool backwash																		
<input type="checkbox"/> Piers																				
DETERMINATION OF CERTIFICATE	<p>Wagga Wagga City Council confirms that:</p> <p><input checked="" type="checkbox"/> The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.</p> <p><input checked="" type="checkbox"/> The above condition(s) have been complied with and works can continue.</p> <p><input type="checkbox"/> The Compliance Certificate is FAILED for the following reasons:</p> <div style="border: 1px dotted black; height: 40px; margin-top: 5px;"></div>																			
	<p>Inspection Date: 17/10/2023</p> <p>Name of Council Officer: Singh, Pardeep</p> <p>BDC Registration No: 4867</p> <p>Council User ID: SINGHP</p>																			

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.