



City of Wagga Wagga

INSPECTION REPORT

APPLICANT	LJ Bender 37 Alfred St OURA NSW 2650					
SUBJECT LAND	ADDRESS: 37 Alfred St OURA NSW 2650 LOT/DP: Lot 9 Sec 13 DP 758819					
CERTIFICATE NO.	CC23/0242		DATE OF ISSUE: 12/10/2023			
TYPE OF CERTIFICATE	<input checked="" type="checkbox"/> Specified building/subdivision work has been completed and complies with the plans and specifications.					
	<input type="checkbox"/>	Footing	<input type="checkbox"/>	Frame	<input checked="" type="checkbox"/>	Floor Slab
	<input type="checkbox"/>	Wet area flashing	<input type="checkbox"/>	Sub floor frame	<input type="checkbox"/>	Stormwater drainage
	<input type="checkbox"/>	Internal drainage	<input type="checkbox"/>	External drainage	<input type="checkbox"/>	Trade Waste
	<input type="checkbox"/>	Stackwork	<input type="checkbox"/>	Final plumbing	<input type="checkbox"/>	Pool backwash
	<input checked="" type="checkbox"/>	Piers				
	Other <input checked="" type="checkbox"/> Conditions have been complied with Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with. <div style="border: 1px dashed black; padding: 5px;"> Comments: 600 DIA piers / 100mm slab for the new shed satisfactory. complete building and connect storm water under section 68 AA approval. </div>					
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that: <input checked="" type="checkbox"/> The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above. <input checked="" type="checkbox"/> The above condition(s) have been complied with and works can continue. <input type="checkbox"/> The Compliance Certificate is FAILED for the following reasons: <div style="border: 1px dashed black; height: 30px; width: 100%;"></div>					
	Inspection Date: 03/11/2023 Name of Council Officer: Stanic, Luka BDC Registration No: 2359 Council User ID: stanicl					

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.