



City of Wagga Wagga

INSPECTION REPORT

APPLICANT	Matt Jenkins Builder Pty Ltd 18 Dobney Ave WAGGA WAGGA NSW 2650					
SUBJECT LAND	ADDRESS: 7 Paroo PI TATTON NSW 2650 LOT/DP: Lot 27 DP 1291851					
CERTIFICATE NO.	CC23/0234		DATE OF ISSUE: 08/06/2023			
TYPE OF CERTIFICATE	<input type="checkbox"/> Specified building/subdivision work has been completed and complies with the plans and specifications.					
	<input type="checkbox"/>	Footing	<input type="checkbox"/>	Frame	<input type="checkbox"/>	Floor Slab
	<input checked="" type="checkbox"/>	Wet area flashing	<input type="checkbox"/>	Sub floor frame	<input type="checkbox"/>	Stormwater drainage
	<input type="checkbox"/>	Internal drainage	<input type="checkbox"/>	External drainage	<input type="checkbox"/>	Trade Waste
	<input type="checkbox"/>	Stackwork	<input type="checkbox"/>	Final plumbing	<input type="checkbox"/>	Pool backwash
	<input type="checkbox"/>	Piers				
	Other					
	<input type="checkbox"/> Conditions have been complied with					
	Give details of the specified condition(s) of the development <u>or</u> complying development certificate and detail the matter the condition relates to and the standards/instruments that the matter is required to comply with.					
DETERMINATION OF CERTIFICATE	Wagga Wagga City Council confirms that:					
	<input type="checkbox"/> The above described building/subdivision work has been completed and complies with the attached plans and specifications and the above described aspect of development complies with the prescribed requirement referred to above.					
	<input type="checkbox"/> The above condition(s) have been complied with and works can continue.					
	<input checked="" type="checkbox"/> The Compliance Certificate is FAILED for the following reasons:					
	Comments: Ensure puddle flanges are installed as discussed to all floor wastes, a re inspection will be required to ensure puddle flanges are installed to the NCC 2022					
	Inspection Date: 29/11/2023					
	Name of Council Officer: Foster, Kira-Lee					
	BDC Registration No: 0974					
	Council User ID: fosterk					

NOTE: This inspection was completed using an electronic device

This inspection report is not a certificate under Part 4A of the Environmental Planning and Assessment Act 1979.